




DIFFICULTY LEVEL

SHAD

BCN

MOTO MORINI X-CAPE 1200 '25-

TOP MASTER
M0XC16ST



1 263879 x1



2 261121 x4
Ø20 Ø11 x 18



3 303045 x2
Ø8



4 303027 x2
Ø8



5 304039 x2
M8x40 DIN 7380



6 304356 x2
M8x40 DIN 7991

WARNING!







(GB) Do not fully tighten the screws until it is ensured that the KIT is correctly attached and aligned. Check tightness every 4 months.

(E) No apretar los tornillos del todo hasta asegurarse que el KIT está correctamente colocado y alineado. Repasar apriete cada 4 meses.

(D) Ziehen Sie die Schrauben nicht ganz fest, bevor Sie sich nicht vergewissert haben, daß der Bausatz korrekt eingestellt und ausgerichtet ist. Alle 4 Monate Drehmoment überprüfen.

(I) Non stringere del tutto le viti fin tanto non si è sicuri che il kit è collocato correttamente e allineato. Controllare il serraggio delle viti ogni 4 mesi.

(F) Ne pas serrer les vis avant d'être sûr que le KIT soit correctement positionné et ajusté. Vérifier le serrage des vis tous les 4 mois.



WWW.SHAD.ES

REF. 500479 Edition 1ª

IMPORTANT: Based on European models. For compatibility with models in other continents, check www.shad.es